Troubleshooting

Model: SD-D58 series

■Product abnormalities

= 1 Todade do Horitanico				
Symptom/display	FAULT lamp	Cause	Corrective action	
The power cannot be turned on.	_	The wiring is not correct.	Connect the wiring properly.	
		The terminal plate is removed.	Connect the terminal plate properly.	
		Abnormalities/momentar y blackout of power supply system	Provide the rated voltage. Take measures such as checking or adding the UPS, power supply line filter and insulation transformer.	
		Cable abnormalities (open circuit/not connected/short circuit)	Check the wiring of detector head and related devices around it.	
Abnormal operations		Disturbances by sudden surge noise, etc.	Turn off and restart the detector head. If such a symptom is observed frequently, take appropriate measures to eliminate the noise.	

■Reading abnormalities

Symptom	Cause	Corrective action
	Drifting of sensor output	Perform the zero adjustment.
The reading rises	Presence of interference gas	Disturbances by interference gases, such as solvents, cannot be eliminated completely. For information on actions, such as removal filter, please contact distributor.
(drops) and it remains so.	Slow leak	A very small amount of the gas to be detected may be leaking (slow leak). Because ignoring it may cause dangers, take a remedial measure, i.e., taking actions the same as those for the gas alarm.
	Environmental changes	Perform the zero adjustment (AIR adjustment).
	Presence of interference gas	Disturbances by interference gases, such as solvents, cannot be eliminated completely. For information on actions, such as removal filter, please contact distributor.
A gas alarm is triggered despite of no gas leak and no other	Disturbance by noise	Turn off and restart the detector head. If such a symptom is observed frequently, take appropriate measures to eliminate the noise.
abnormalities at the detection point.	Sudden change in the environment	When the environment (temperature, etc.) changes suddenly, the detector head cannot adjust to it and is affected by it. In some cases, the detector head triggers an indication alarm. Because the detector head cannot be used under sudden and frequent environmental changes, you must take any preventive actions to eliminate them.
Slow response	Deteriorated sensor sensitivity	Replace the sensor with a new one.
Span adjustment	Improper calibration gas concentration	Use the proper calibration gas.
impossible	Sensor sensitivity deterioration	Replace the sensor with a new one.